



For much more on flying safely see www.thomaspturner.net.

©2009 Mastery Flight Training, Inc. All rights reserved

FLYING LESSONS for February 5, 2009

suggested by this week's mishap reports

FLYING LESSONS uses the past week's mishap reports as the jumping-off point to consider what *might* have contributed to accidents, so you can make better decisions if you face similar circumstances. In almost all cases design characteristics of a specific make and model airplane have little direct bearing on the possible causes of aircraft accidents, so apply these *FLYING LESSONS* to any airplane you fly. Verify all technical information before applying it to your aircraft or operation, with manufacturers' data and recommendations taking precedence.

Feel free to forward this message for the purpose of pilot education. *FLYING LESSONS* is also available in PDF through a link in the left column at www.thomaspturner.net.

FLYING LESSONS is an independent product of Mastery Flight Training, Inc.



FLYING LESSONS is featured on the FAA's safety website!

See www.faa.gov/gslac/ALC/lib_categoryview.aspx?categoryId=21.

This week's lessons:

FAA has revised what it means to have "known icing" conditions, as a result of a query from AOPA. The revised definition improves flight planning flexibility by placing ice-related flight planning authority squarely in the hands of the pilot-in-command. Just as earning your instrument rating means you have to work harder to plan a flight, so too does this new definition require us to see and know more to exercise our authority to fly in cold-weather IMC. *FLYING LESSONS* looks at the new definition and its implications later in this issue. First, however, let's learn from some recent ice-related accidents.

Attempting to overfly icy clouds works only as long as you have a way down without flying through them. Reference this recent NTSB report:

The pilot stated he flew the en route portion of the flight...at 9,000 feet above mean sea level (msl) and that the cloud tops were at 6,500 msl. He was in contact with...approach control when nearing [his planned destination]. He stated the only pilot report regarding icing was from an airplane over Lake Michigan.

The pilot was cleared for the GPS approach and the airplane picked up light rime ice during the descent through the clouds, breaking out of the clouds around 1,700 msl (900 above ground level). He stated he had the pitot head [sic] and defrosters on, but he was unable to see out of the forward windscreen so he had to look out the side window during the landing. He stated he maintained as much airspeed as possible until the airplane contacted the frozen river. The pilot reported the airplane normally stalls at 62 knots; however, it stalled at 82 knots during the landing.

Turbo power isn't a panacea, either. The same report continues:

The pilot reported that as he neared the airport he attempted to add engine power, but was able to maintain only 17 inches of manifold pressure.

Commonly when an engine's alternate induction air source is in the lower, low-pressure area of an engine compartment, if the inlet air filter clogs with ice or snow the induction air pressure is low enough the turbocharger cannot provide full power. Further, when iced the propeller becomes less efficient at turning power into thrust, and the wings and tail become aerodynamic unknowns. What has been said about the effects of density altitude on airplane performance goes for airframe ice accumulation as well—you can't turbocharge the propeller, wings or tail.

Nor is “known ice” certification a guarantee, as the pilot of this turbocharged and ice-certificated twin found:

The pilot reported that during a cross-country flight conducted under instrument flight rules, he encountered clouds that contained clear ice. Ice built up rapidly on the airplane, which was in cruise flight at 16,000 feet. In an effort to get out of the icing conditions, he requested and received clearance to progressively lower altitudes down to 10,000 feet. The airplane continued to accumulate ice. He requested a turn, and this was denied by the controller as there were two other airplanes in the vicinity with similar icing problems. He then requested and received clearance to descend to 9,000 feet, where he could see portions of the ground. At this point, “both windshields were completely covered with clear ice as were the unprotected portions of the aircraft” and both engines were operating at full power. The pilot informed the controller that he needed to descend further. At an altitude of 7,500 feet, he circled several times attempting to see if he could reach an airport for landing. No ice had melted or come off the airplane, and the weather was deteriorating. The pilot decided to land on a highway. On final approach to land, the airplane collided with a power line, which severed the upper half of the rudder and vertical stabilizer. The pilot turned the airplane slightly left, and landed the airplane with the landing gear down in a terraced field next to the highway. During the landing roll, the landing gear was sheared off when the airplane encountered a ditch. The pilot stated that he had “no forward visibility due to the clear ice that completely covered the windshields.”

Landing an ice-laden airplane can be tricky. Read this report:

The pilot reported that during the flight he encountered unforecasted freezing rain. He questioned air traffic control about the weather and was told that they were not showing any precipitation. The pilot requested and received a descent to a lower altitude to stay below the clouds. The airplane's airspeed continued to decrease and the pilot informed air traffic control that he wanted to divert to a nearby airport. The pilot made two low passes over the airport while trying to clear ice off of the windshield; however, the windshield alcohol de-ice could not keep up with the ice accumulation. The pilot stated he had to look out of the side window during the landing and once he descended below the tree line, he was unable to accurately judge his height over the runway. He stated this was compounded by the light color of the new concrete runway which had snow blowing across it. A hard landing resulted. The right wing strut was bent and the wing was pushed into the fuselage during the landing.

Anti-ice protection, like most alcohol-based systems (except TKS), is designed to prevent formation of light amounts of ice, must be turned on before ice begins to form, and is generally incapable of preventing “moderate” or greater ice accumulation or any flight in freezing rain or supercooled large droplets (more on this in a minute). Turn it on before you enter *suspected* icing conditions, and be ready to exercise your preplanned ice escape route if any ice begins to form.

The FAA's Small Airplane Directorate recently published a [General Aviation Safety Challenge](#) report on ice that includes:

- Standards used to certificate airplanes for icing do NOT cover all possible icing conditions. The standards only cover some of the water forms that can exist in clouds. Icing conditions can overwhelm your ice protection.
- Certification standards assume you will hold in icing conditions less than 45 minutes. Pilots of aircraft certificated for flight in icing conditions should not be casual about operations in those conditions - particularly extended operations.
- More importantly, certification standards do NOT include supercooled large droplet (SLD) icing. SLD will impinge farther aft on the wing and tail, forming ice behind your de-icing boots or other ice-protection system. The aerodynamic penalties can be larger than what comes from ice that forms on leading edges.
- Learn the cues and exit procedures of severe icing for your airplane. If your airplane's pilot's operating handbook (POH) or airplane flight manual (AFM) does not have any, consult [Advisory Circular 91-74A](#) "Pilot Guide: Flight in Icing Conditions" for cues and exit procedures.
- Some airplanes may exhibit little visual cues, such as side-window icing. On single-engine airplanes, spinner ice, which may provide a cue in multiengine airplanes, cannot be seen by the pilot. It is important to look for indications of drizzle and rain, such as drops that splatter on your windshield. In a certification flight test of a single-engine turboprop, the only indication of SLD, which resulted in nodules of ice covering the underside of the wing, was a noticeable increase in required power to maintain the approach glide slope.
- What certification testing is done to show airplanes without ice protection equipment can safely exit an inadvertent icing encounter? The answer is simple – **NONE**. There are only requirements for engine induction icing and pitot and static source ice protection for IFR approved airplanes.
- Most icing encounters are of low water content and drop size, so if you have safely exited one encounter, or hear hangar talk that your airplane is okay in icing, don't gamble that the next encounter will have the same result.

The Challenge continues:

- Icing certification standards have changed dramatically over the years. Prior to 1973, small airplanes were not required to test in icing conditions nor be analyzed or tested to the icing condition standard used today. The standards have changed significantly, even in the last few years. Advisory Circular 91-74A provides a good history for those who want more information.
- The two major changes are in stall warning and climb performance. Small airplanes certificated prior to 2000 were given certification credit for natural aerodynamic stall warning (buffet) even if the airplane was equipped with a stall-warning system. Since ice buildup on the wing lowers the stall angle of attack, the stall-warning sensor might not provide warning in icing conditions. Pilots therefore should know the POH/AFM minimum icing airspeeds and treat them as limitations, even if they are not in the Limitations section.
- If your POH/AFM does not have minimum icing airspeeds, add 15 to 20 knots indicated airspeed to your normal operating airspeed. This goes for all phases of flight, including approach and landing, where most small airplane icing accidents

occur. Also, treat any buffet or vibration as an impending wing stall, and limit maneuvering in icing conditions.

- Likewise, prior to 1993, there were no quantitative requirements for climb performance in icing conditions. An airplane being certificated today is required to have en route climb performance data in the POH/AFM if the airplane's service ceiling in icing is less than 22,000 feet. Pilots should consider the climb performance of the airplane and the route's minimum altitude when determining routes and exit strategies in preflight planning. The airplane's climb performance will be degraded in icing conditions. Consider climbing or descending to take yourself out of icing.
- However, don't assume you can climb with ice on your airplane. If you cannot climb to exit icing, do not fly below the minimum airspeed in icing. Exit by making a 180-degree turn, or, if you cannot maintain altitude in icing at your minimum airspeed, trade altitude to keep airspeed above the minimum airspeed in icing.
- Airplane certification assumes the airplane is clean on takeoff. The ability to safely take off with contamination, including polished frost, is not tested. No airplane manufacturer, nor the FAA, has an established procedure for polishing frost, and the lift and drag penalties are unknown. Taking off with any contamination reduces the already small stall margin and reduces climb performance. Make sure critical surfaces such as lifting surfaces, control surfaces, propeller blades, and engine inlets are free of contamination.

See:

www.faa.gov/files/notices/2008/Nov/GAIcing.pdf

[http://rql.faa.gov/Regulatory_and_Guidance_Library/rqAdvisoryCircular.nsf/0/4c8192bb0b733862862573d2005e7151/\\$FILE/AC%2091-74A.pdf](http://rql.faa.gov/Regulatory_and_Guidance_Library/rqAdvisoryCircular.nsf/0/4c8192bb0b733862862573d2005e7151/$FILE/AC%2091-74A.pdf)

Learn more about predicting ice with these resources:

- The [Aviation Weather Center](#)
- FAA Advisory Circular 91-74A, "[Pilot Guide: Flight in Icing Conditions](#)"
- AOPA's free "[Weatherwise](#)" [Precipitation and Icing](#)" online course
- [Cessna Aircraft's e-Learning](#) Caravan pilot ice certification course, required to have been completed by the PIC within the previous 12 months for the C208's "known ice" certification to be valid. Although many parts of this program are airplane type-specific, it's superbly detailed coverage of what is, and is not, meant by approval for flight in icing conditions regardless of the airplane you fly.
- [Cirrus Design's announced Icing Awareness training program](#), optimized for the soon-to-be-certified "known ice" SR22 Turbo variant and, like the Caravan course, an integral part of the airplane's flight-in-ice certification (Are you a reader at Cirrus who can forward information about enrolling in the course? Please email mastery.flight.training@cox.net)
- [Chesapeake Aviation Training](#)'s Aviation Weather Workshops

See:

<http://aviationweather.gov/>

http://flash.aopa.org/asf/wxwise_precip/

www.cessnaelearning.com/index.aspx

www.webwire.com/ViewPressRel.asp?ald=84606

<http://chesavtraining.com/>

Questions? Comments? Email me at mastery.flight.training@cox.net

More on FAA's new "known ice" definition

[AOPA](#) posts an [interpretation of the new definition of "known ice"](#) on its website, including a copy of the actual [FAA letter](#) explaining the new "known ice" rule. The FAA letter states:

Any assessment of known icing conditions is necessarily fact-specific. Permutations on the type, combination, and strength of meteorological elements that signify or negate the presence of known icing conditions are too numerous to describe exhaustively in [the FAA's] letter. Whether a pilot has operated into known icing conditions contrary to any [aircraft] limitation will depend on the total information available to the pilot, and his or her proper analysis of that information in evaluating the risk of encountering known icing conditions during a particular operation. The pilot should consider factors such as the route of flight, flight altitude and time of flight when making such an evaluation.

FAA lists these products, at a minimum, as those a "prudent" pilot would evaluate to determine there is no likelihood of airframe ice accumulation:

- Surface observations [METARs]
- Temperatures aloft
- Terminal forecasts [TAFs]
- Area forecasts
- AIRMETs
- SIGMETs
- Pilot Reports

FAA also states "As new technology becomes available, pilots should incorporate the use that technology into their decision-making process." Examples include the Current Icing Potential ([CIP](#)), Forecast Icing Potential ([CIP](#)) and similar products.

What does this all mean? From the FAA:

If the composite [of available weather] information indicates to a reasonable and prudent pilot that he or she will be operating the aircraft under conditions that will cause ice to adhere to the aircraft along the proposed route and altitude of flight, then known icing conditions likely exist. If the pilot operates the aircraft in known icing conditions contrary to the requirements of [FAR] 91.9(a), the FAA may take enforcement action.

The FAA concludes:

Pilots should not expose themselves or others to the risk associated with flight into conditions in which ice is likely to adhere to an aircraft. If ice is detected or observed along the route of flight, the pilot should have a viable exist strategy and immediately implement or terminate at [deviate to] an alternate landing facility. If icing is encountered by a pilot when operating an aircraft not approved or equipped for flight in known icing conditions, the FAA strongly encourages the submission of PIREPs and immediate requests to ATC for assistance. Such actions can significantly enhance safety, reduce accidents, and benefit the entire aviation community.

The new FAA definition of "known icing conditions", then, provides greater flexibility to pilots planning flights in areas of below-freezing conditions, and places responsibility on the pilot-in-command (where it should be) to actively plan a route and altitude that will keep his or her aircraft out of conditions of visible moisture in the range of temperatures and conditions conducive to airframe ice accumulation. It is **not** blanket approval to "climb through" or descend into reported or "prudently"-anticipated icing conditions in airplanes unequipped for or prohibited from flight in icing conditions.

FAA's interpretation is entirely consistent with most aviation mentors, instructors and training providers' advice to "always have an out" when faced with the possibility weather reports or the pilot's planning may prove wrong and actual icing conditions exist. It also confirms **FLYING LESSONS'** frequent teaching to treat the first sign of ice accumulation just as you would an unexpected sounding of the stall warning horn—an indication you must do something different *now* to escape icing conditions and remove the ice that has already formed, whether your airplane is certified for flight in ice or not.

See:

www.aopa.org/advocacy/articles/2009/090128icing.html?WT.adv=adv2
<http://download.aopa.org/epilot/2009/090126icing.pdf>
<http://adds.aviationweather.gov/icing/description3.php>
<http://adds.aviationweather.gov/icing/description4.php>

For piston Beech pilots

The February 5, 2009 Weekly Accident Update is now posted at www.thomaspturner.net, including these reports:

- A K35 landed gear up....
- An A36's landing gear collapsed....
- A G35 landed gear up....
- A B55's landing gear collapsed....

There are also NTSB updates on two airframe ice-related events.

For more information, commentary and analysis see the Beech Weekly Accident Update link at www.thomaspturner.net/WAU_2009.htm.

Fly safe, and have fun!

Thomas P. Turner, M.S. Aviation Safety MCFI
2008 FAA Central Region Flight Instructor of the Year

I welcome your comments and suggestions. Contact mastery.flight.training@cox.net.

If someone has forwarded this message to you and you want to have *FLYING LESSONS* sent directly to you each week, [tell me](#). If you received this message directly (as opposed to through a digest or chat room) and wish to be removed from the *FLYING LESSONS* list, [tell me](#).

©2009 Mastery Flight Training, Inc. All rights reserved.



Holder of an ATP certificate with instructor, CFII and MEI ratings and a Masters Degree in Aviation Safety, and **2008 FAA Central Region CFI of the Year**, Master CFI Thomas P. Turner has been Lead Instructor for FlightSafety International's Bonanza pilot training program at the Beechcraft factory; production test pilot for engine modifications; aviation insurance underwriter; corporate pilot and safety expert; Captain in the United States Air Force; and contract course developer for Embry-Riddle Aeronautical University. He is now the Manager of Technical Services for the American Bonanza Society. With over 3600 hours logged, including more than 2200 as an instructor, Tom writes, lectures and instructs extensively from his home at THE AIR CAPITAL--Wichita, Kansas.

